JUL 13 2020

REQUEST FOR AGENDA Submission Deadline - Tuesday,	
SUBMITTED BY: Ralph McBroom TODAY'S DATE: July 7, 2020	
DEPARTMENT: Purchasing	
SIGNATURE OF DEPARTMENT HEAD	:
REQUESTED AGENDA DATE: July 1	3, 2020
SPECIFIC AGENDA WORDING: Consideration system addition to the Johnson County Jail Sourcewell Cooperative Contract Number system addition includes gate locks, gate cocheck in for Building C4 to be integrated were supplied to the system addition of the system additional system.	l from Stanley Security under The 031517 for \$107,367.73. The security ontrols and cameras to enable overnight
which is located in Building C1.	
PERSON(S) TO PRESENT ITEM:	Ralph McBroom C.P.M.
SUPPORT MATERIAL: (See attached)	
TIME: 5 min	ACTION ITEM: X WORKSHOP
(Anticipated number of minutes needed to discuss item	n) CONSENT: EXECUTIVE:
STAFF NOTICE:	
AUDITOR: PERSONNEL:	IT DEPARTMENT: PURCHASING DEPARTMENT: PUBLIC WORKS: OTHER: SO
*********This Section to be completed	by County Judge's Office********
	AGENDA DATE: TY JUDGE'S OFFICE
COURT MEMBER APPROVAL	Date

STANLEY Convergent Security Solutions 11823 Starcrest Drive, San Antonio, TX 78247

To:	J. Loftin (214-604-7166)	
	Ralph Mc Broom (214-542-5173)	
Organization:	Organization: LaSalle Southwest Corrections	
Bus. Phone:		
Fax or Email:	<u>Jloftin@johnsoncountyTX.org</u>	
	Ramcbroom@johnsoncountytx.org	

QUOTATION Q200137 (Rev2)

Johnson Co. Correctional Gate Addition

7/1/2020

Sourcewell Contract #031517-SCS Maturity Date: 06/30/2021

SCOPE OF WORK

Stanley will provide (Narrative):

- 1. Provide and install (4) Southern Folger 1050D-2 120VAC solenoid gate locks (note: Manufacturing lead time is 10-14 weeks from date of receipt of approved submittals)
- 2. Provide two keys per lock
- 3. Provide PLC processor, input/output cards, power supplies in Building C4's A110 electronics racks
- 4. Provide relays to control new gates
- 5. Provide door cabling from A110 to each gate
- 6. Provide intercom cabling from A110 to each intercom station
- 7. Integration and control of the new locks and intercom stations with the existing touchscreen control system
- 8. Provide 7 exterior cameras mounted on the C4 building
- 9. Provide 1 exterior camera mounted on the gate fence
- 10. Provide conduit to exterior devices (rigid conduit mounted on fence then EMT in attic for the gate equipment)
- 11. Interior devices will use plenum wire in the attic without conduit

Equipment:

Δ	/ 4 \	Gate	_ 1 1
I ITM	1711	(- 314	2 1000

Qty (6)..... Intercom stations

Qty (8)..... Cameras

Qty (1 Lot)... Wire and wire installation

Qty (1 Lot)... Engineering

Qty (1 Lot)... Programming and configuration into the existing touchscreen control system

Qty (1 Lot)... Testing

Qty (1 Lot)... Training while on-site

Exclusions:

- 1. Chain link fence and gates
- 2. Finish paint and touchup paint
- 3. Bond and bond premium
- 4. All building permits and fees
- 5. Multiple mobilizations
- 6. Repair or replacement of existing field devices that are to be re-used
- 7. Repair or replacement of existing wire that is to be re-used
- 8. Adjustments and/or troubleshooting of existing non-functional devices. These can be quoted on a time and material basis in addition
- 9. 120VAC power hookup
- 10. Grounding

STANLEY Convergent Security Solutions 11823 Starcrest Drive, San Antonio, TX 78247

- 11. Lifts or ladders. We expect to use the owner's
- 12. Taking in and bringing out our tools and equipment each day. We need a secure place inside the facility to store these items during our work on-site
- 13. UPS systems

Timeline and Schedule:

After receipt of order, we will schedule the work around availability and access to the jobsite.

Pricing:

This quote (County is Tax Exempt) Performance and Payment Bond	Price \$106,304.68Add \$1,063.05
Total Price	Total Price \$107,367.73

If you have any questions, please feel free to call.

Sincerely,

David Beeler

Senior Sales Engineer STANLEY Convergent Security Solutions, Inc.

11823 Starcrest Drive, San Antonio, TX 78247 **C:** 317-796-6241 **Service**: 866-614-4175

david.beeler@sbdinc.com | www.stanleysecuritysolutions.com/Corrections