

# SUMMARY OF SALIENT FEATURES

Approved by CC:

JAN 18 2014

<b>SUBJECT INFORMATION</b>	Subject Address	116 S Mill St
	Legal Description	Lots 1, 2, 3, 4, Block 11, Original Cleburne
	City	Cleburne
	County	Johnson
	State	TX
	Zip Code	76033
	Census Tract	48251-1308.00
	Map Reference	JohnsonMpsco1116X
<b>SALES PRICE</b>	Sale Price	\$ NA
	Date of Sale	NA
<b>CLIENT</b>	Owner	Johnson County
	Client	Johnson County
<b>DESCRIPTION OF IMPROVEMENTS</b>	Size (Square Feet)	15,042
	Price per Square Foot	\$ 10.11
	Location	Central Business District
	Age	~1885 per Sanborn Map
	Condition	Poor to Fair
	Total Rooms	70
	Bedrooms	36 Cells, 9 Offices, 1 Kitchen, 2 Dining, 13 Other
	Baths	9 Restrooms, plus multiple restroom facilities for the cell blocks
<b>APPRAISER</b>	Appraiser	Dona L Buie, ATA-G
	Date of Appraised Value	9/26/2013
<b>VALUE</b>	Opinion of Value	\$ 152,000

## Engagement Letter

Owner	Johnson County			
Property Address	116 S Mill St			
City	Cleburne	County	Johnson	State TX Zip Code 76033
Client	Johnson County			

Hello Ms. Buie,

Johnson County is considering the sale of five (5) pieces of property pending Commissioners Court approval. We are requesting a soft quote from RFP2011-417: Real Estate Appraiser Services for the properties listed below. We are also requesting an estimated start date upon notification to proceed as well as an estimated time of completion.

### Property Location

113-121 W. Chambers, Cleburne, TX 76031; 1-story 4131 sq. ft. building (Annex)  
104 S. Main Str., Cleburne, TX 76031; 2-story 5632 sq. ft. building (Lesial)  
116 S. Mill Str., Cleburne, TX 76031, 3-story 14441 sq. ft. building (Old Jail)  
102 S. Main Str., Cleburne, TX 76031, 2-story 10164 sq. ft. building (Old Adult Probation)  
102 E. Chambers St., Cleburne, TX 76033, .1600 acre parking lot


Please do not hesitate to contact Kelli or me if you have any questions or need any additional information.

Sincerely,

Heather Carmichael  
Contract Manager/Buyer  
Johnson County Purchasing  
1102 E Kilpatrick, Ste B  
Cleburne, TX 76031  
(817) 556-6384 phone  
(817) 556-6385 fax

# State of Texas Map


Owner	Johnson County			
Property Address	116 S Mill St			
City	Cleburne	County Johnson	State TX	Zip Code 76033
Client	Johnson County			



© geology.com


# County of Johnson Map

Owner	Johnson County			
Property Address	116 S Mill St			
City	Cleburne	County	Johnson	State TX Zip Code 76033
Client	Johnson County			



# City of Cleburne Map

Owner	Johnson County			
Property Address	116 S Mill St			
City	Cleburne	County	Johnson	State TX      Zip Code 76033
Client	Johnson County			




# Business Centers Map

Owner	Johnson County		
Property Address	116 S Mill St		
City	Cleburne	County Johnson	State TX Zip Code 76033
Client	Johnson County		



# Location Map

Owner	Johnson County			
Property Address	116 S Mill St			
City	Cleburne	County	Johnson	State TX      Zip Code 76033
Client	Johnson County			




# Zoning Map

Owner	Johnson County			
Property Address	116 S Mill St			
City	Cleburne	County	Johnson	State TX Zip Code 76033
Client	Johnson County			

**C1**

according to map provided by P&Z






# Location Map

Owner	Johnson County		
Property Address	116 S Mill St		
City	Cleburne	County Johnson	State TX      Zip Code 76033
Client	Johnson County		

**InterFlood**  by a la mode  
 www.interflood.com • 1-800-252-6633

**Prepared for:**  
 Appraisal Associates  
 W Chambers & Mill St  
 Cleburne, TX 76031



**FLOODSCAPE**  
**Flood Hazards Map**  
 Map Number  
 48251C0285J  
 Effective Date  
 December 4, 2012


Powered by FloodSource  
 877.77.FLOOD  
 www.floodsource.com

© 1999-2013 SourceProse and/or FloodSource Corporations. All rights reserved. Patents 6,631,326 and 6,678,615. Other patents pending. For info: info@floodsource.com.

# Sanborn Map 1885




# Aerial View of Building



# Site Map


Owner	Johnson County		
Property Address	116 S Mill St		
City	Cleburne	County	Johnson
Client	Johnson County	State	TX
		Zip Code	76033

From P&Z office  
The location of the subject site is indicated below



# Building Sketch

Owner	Johnson County			
Property Address	116 S Mill St			
City	Cleburne	County Johnson	State TX	Zip Code 76033
Client	Johnson County			




TOTAL Sketch by a la mode, inc.

Area Calculations Summary	
Living Area	
First Floor	8416.4 Sq ft
<b>Total Living Area (Rounded):</b>	<b>8416 Sq ft</b>
Non-Living Area	
Open Porch	164.3 Sq ft

# Building Sketch

Owner	Johnson County		
Property Address	116 S Mill St		
City	Cleburne	County Johnson	State TX      Zip Code 76033
Client	Johnson County		




TOTAL Sketch by a la mode, inc.

### Area Calculations Summary

Living Area	
Second Floor	3401.1 Sq ft
Third Floor	3224.8 Sq ft
<b>Total Living Area (Rounded):</b>	<b>6626 Sq ft</b>

## Photograph Addendum


Owner	Johnson County			
Property Address	116 S Mill St			
City	Cleburne	County Johnson	State TX	Zip Code 76033
Client	Johnson County			




**Front**



**Street, view N**




**Street, view S**



**N Side**



**N Side**




**N Side**



**N Side**



**N Side**



**N Side**



**N Side**




**Rear**




**Rear**

# Photograph Addendum

Owner	Johnson County						
Property Address	116 S Mill St						
City	Cleburne	County	Johnson	State	TX	Zip Code	76033
Client	Johnson County						



**S Side**



**S Side**




**S Side**



**S Side**




**S Side**



**S Side**




**View of parking/other sheds**




**Basement Mechanical Room**



**Mech room**



**Mech room**



**Mech room**




**Basement Storage**




# Photograph Addendum

Owner	Johnson County						
Property Address	116 S Mill St						
City	Cleburne	County	Johnson	State	TX	Zip Code	76033
Client	Johnson County						




**Stg**




**Basement**



**Basement**



**Basement RR**



**Basement cell**



**Basement Stg**



**Basement Stg**




**Basement Stg**




**Mold on wall**



**Basement Office**




**Basement Hallway**




**Basement Holding area**

# Photograph Addendum

Owner	Johnson County		
Property Address	116 S Mill St		
City	Cleburne	County Johnson	State TX Zip Code 76033
Client	Johnson County		




**Basement Stg closet**




**Stg**



**Cell**




**Cell**



**Dayroom**



**Stairwell, 2nd flr to rear**



**Office**




**Fire equipment closet**




**RR**



**Lobby 2nd floor**




**Plaque, reno 1977**




**Bath between offices 2nd flr**

# Photograph Addendum

Owner	Johnson County			
Property Address	116 S Mill St			
City	Cleburne	County Johnson	State TX	Zip Code 76033
Client	Johnson County			




**Office**



**Office**



**Conference**



**Reception**




**RR**




**RR**




**Kitchen**



**Hallway**




**crack in S wall**



**crack in S wall**




**Hallway**




**Entry from S side**

# Photograph Addendum


Owner	Johnson County						
Property Address	116 S Mill St						
City	Cleburne	County	Johnson	State	TX	Zip Code	76033
Client	Johnson County						




**Room**




**Rec Room, ceiling tiles falling**




**Cells**



**Shower**




**Equipment closet**




**Cell**




**Cell**



**Hallway**




**Equipment closet**



**Hallway**



**Cells**



**Control Room**

# Photograph Addendum

Owner	Johnson County		
Property Address	116 S Mill St		
City	Cleburne	County Johnson	State TX Zip Code 76033
Client	Johnson County		




**Electrical & Storage**



**Cell**



**Cell**




**Hallway**




**Crack in slab, insect activity**



**Stairwell 2nd floor to basement**



**Stairwell, 3rd floor to 2nd floor**




**peeling paint interior**



**Office**




**Cells**



**Cells**

## Photograph Addendum

Owner	Johnson County			
Property Address	116 S Mill St			
City	Cleburne	County	Johnson	State TX Zip Code 76033
Client	Johnson County			



**Cells**



**Dining**




**Stg Closet with sink**



**Storage**

## Comparable Building Photos

Owner	Johnson County						
Property Address	116 S Mill St						
City	Cleburne	County	Johnson	State	TX	Zip Code	76033
Client	Johnson County						



### **319 E Henderson St**

Cleburne, TX


unrenovated industrial building



### **116 W Knox St**

Ennis, TX

unrenovated older building




### **116 S Covington St**

Hillsboro, TX

Unrenovated retail/office space

# Comparable Sales Map

Owner	Johnson County		
Property Address	116 S Mill St		
City	Cleburne	County Johnson	State TX      Zip Code 76033
Client	Johnson County		





## Comparable Rentals Photograph Addendum


Owner	Johnson County			
Property Address	116 S Mill St			
City	Cleburne	County	Johnson	State TX Zip Code 76033
Client	Johnson County			



### **216 S Main**

Cleburne, TX

Retail space needed updating & repairs



### **110 E Chambers**

Cleburne, TX

Retail space needed updating & repairs  
only bottom floor can be occupied currently per agent




### **206 S Main St**

Cleburne, TX

Retail space needed updating & repairs

# Comparable Rentals Map

Owner	Johnson County			
Property Address	116 S Mill St			
City	Cleburne	County	Johnson	State TX      Zip Code 76033
Client	Johnson County			



## **PRIVACY NOTICE**

**Pursuant to the Gramm-Leach-Bliley Act of 1999, effective July 1, 2001, Appraisers, along with all providers of personal financial services are now required by federal law to inform their clients of the policies of the firm with regard to the privacy of client nonpublic personal information. As professionals, we understand that your privacy is very important to you and are pleased to provide you with this information.**

### **Types of Nonpublic Personal Information We Collect**

In the course of performing appraisals, we may collect what is known as "nonpublic personal information" about you. This information is used to facilitate the services that we provide to you and may include the information provided to us by you directly or received by us from others with your authorization.

### **Parties to Whom We Disclose Information**

We do not disclose any nonpublic personal information obtained in the course of our engagement with our clients to nonaffiliated third parties, except as necessary or as required by law. By way of example, a necessary disclosure would be to our employees, and in certain situations, to unrelated third party consultants who need to know that information to assist us in providing appraisal services to you. All of our employees and any third party consultants we employ are informed that any information they see as part of an appraisal assignment is to be maintained in strict confidence within the firm.

A disclosure required by law would be a disclosure by us that is ordered by a court of competent jurisdiction with regard to a legal action to which you are a party.

### **Confidentiality and Security**

We will retain records relating to professional services that we have provided to you for a reasonable time so that we are better able to assist you with your needs. In order to protect your nonpublic personal information from unauthorized access by third parties, we maintain physical, electronic and procedural safeguards that comply with our professional standards to insure the security and integrity of your information.

Please feel free to call us any time if you have any questions about the confidentiality of the information that you provide to us.

# APPRAISER DISCLOSURE STATEMENT

File No. 1309-04

**Name of Appraiser:** Dona L Buie, ATA-G

**Class of Certification/Licensure:**  Certified General  
 Certified Residential  
 Licensed Residential  
 Temporary     General     Licensed

**Certification/Licensure Number:** TX-1327327-G

**Certification/Licensure State:** TX    **Expires:** 04/30/2015

**Scope:**    This Report     is within the scope of my Certification or License  
 is not within the scope of my Certification or License

**Service Provided By:**     Disinterested & Unbiased Third Party  
 Interested & Biased Third Party  
 Interested Third Party on Contingent Fee Basis

**Signature of person preparing and reporting the Appraisal:**

Dona L. Buie

This form must be included in conjunction with all appraisal assignments or specialized services performed by a state-certified or state-licensed real estate appraiser.

## Appraiser's License

Owner	Johnson County			
Property Address	116 S Mill St			
City	Cleburne	County	Johnson	State TX Zip Code 76033
Client	Johnson County			

### Texas Appraiser Licensing and Certification Board

P.O. Box 12188 Austin, Texas 78711-2188

#### Certified General Real Estate Appraiser

Number: **TX 1327327 G**

Issued: **03/13/2013**

Expires: **04/30/2015**

Appraiser: **DONA LEE BUIE**

Having provided satisfactory evidence of the qualifications required by the Texas Appraiser Licensing and Certification Act, Texas Occupations Code, Chapter 1103, is authorized to use this title, Certified General Real Estate Appraiser.

  
Douglas E. Oldmixon  
Commissioner

## REAL ESTATE APPRAISAL REPORT

### Property Located At

116 South Mill St  
Cleburne, TX 76031

### Prepared for

Johnson County Judge  
2 N. Main Street, Rm 120  
Cleburne, TX 76031

### Prepared by

Appraisal Associates, LLC  
P. O. Box 391  
Granbury, Texas 76048  
(817) 279-8689 FAX (817) 579-5096

### Effective Date of Appraisal

September 26, 2013

### Appraiser

Dona L. Buie, ATA-G  
State Certified General

\*\*\*\*\*

\*\*\*\*\*

**Appraisal Associates, LLC**  
**State Certified Real Estate Appraisers**  
**P. O. Box 391**  
**Granbury, Texas 76048**  
**Voice: (817) 279-8689 Fax: (817) 579-5096**

December 6, 2013

Heather Carmichael, Contract Mgr/Buyer  
Johnson County  
1102 E Kilpatrick, Ste B  
Cleburne, TX 76031

**RE: 216 South Mill Street**

Dear Ms Carmichael:

As per your request, we have made an inspection and valuation analysis of the above-mentioned property which will be legally described in the following report. The purpose of the investigation was to estimate the current market value of the fee simple estate of the same property, as defined within FIRREA. This is a **Summary Appraisal Report** and is intended to assist the Client in make financial decisions concerning the property.

The intended Users is the County of Johnson, Texas. The subject is not currently listed for sale or sold within the past three years.

This estimate is subject to any contingent and limiting conditions set forth herein. The analyses, opinions, and conclusions were developed, and this report has been prepared in accordance with the Uniform Appraisal Standards and Requirements as set forth by the Appraisal Standards Board. The appraisal report also complies with the Competency provisions of USPAP.

Upon inspection of the property, no other significant, cultural, recreational or scientific value considerations were observed. The value estimates presented in this report address strictly the real property only. Based on information provided to these appraisers and the inspection, the subject property consists of a three story commercial building on 0.506 acres located in the City of Cleburne, County of Johnson, Texas.

The overall condition of the building at this time is considered to be poor to fair. There appears to be ongoing roof leaking and brick/mortar and slab cracks, peeling paint were noted during the inspection of the subject property. An inquiry to the city was made to determine if the building meets current building codes. The city states that there are no code violations or safety issues regarding the property. However, it does not appear to the appraiser that the building is in a condition suited to being leased currently due to what appears to be an ongoing roof leak and many needed repairs. No apparent environmental hazards were noted. However, these appraisers are not experts in the detection of environmental hazards. This report does not contain valuation of any personal property.

Based on our inspection of the neighborhood and analysis of the market area of concern, it is the opinion of the appraiser(s) that a reasonable amount of time allowed for the subject property to be exposed and marketed to the open market would be in the range of two to three years.

By virtue of our investigation, it is the opinion of the appraiser(s) that the Market Value of the fee simple estate of the subject property as described herein, in it's "as is" condition, as of September 26, 2013, was:

**ONE HUNDRED FIFTY TWO THOUSAND DOLLARS**

**( \$ 152,000 )**

Should you have any questions, or if we may be of further assistance to you in the future, please do not hesitate to call on us.

Sincerely yours,

Appraisal Associates, LLC

*Dona L. Buie*

Dona L. Buie, ATA-G  
State Certified General Appraiser



This is a Summary Appraisal Report which is intended to comply with the reporting requirements set forth under Standards Rule 2-2(b) of the Uniform Standards of Professional Appraisal Practice for a Summary Appraisal Report. As such, it presents only summary discussions of the data, reasoning, and analyses that were used in the appraisal process to develop the appraisers' opinion of value. Additional documentation concerning the data, reasoning, and analyses is retained in the appraisers' file. The depth of discussion contained in this report is specific to the needs of the client and for the intended use stated below. The appraisers are not responsible for unauthorized use of this report.

**CLIENT:** Johnson County Judge  
2 N Main Street, Rm 120  
Cleburne, TX 76033

**APPRAISER(S):** Dona L. Buie, State Certified General Appraiser  
Appraisal Associates, LLC  
P. O. Box 391  
Granbury, TX 76048

**SUBJECT:** 116 South Mill Street  
Lot 1, 2, 3 & 4, Block 11, Original Cleburne  
Cleburne, TX 76031

#### **PURPOSE OF THE APPRAISAL**

The objective of this appraisal report is to estimate the Market Value of the fee simple estate of the herein legally described property assuming unencumbered fee simple ownership and on a cash basis.

#### **MARKET VALUE DEFINED**

As used herein, the "Market Value" is defined as the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller, each acting prudently, knowledgeably and assuming the price is not affected by undue stimulus.

Implicit of this definition is the consummation of a sale as of a specified date, and the passing of title from seller to buyer under conditions whereby:

1. Buyer and seller are typically motivated.
2. Both parties are well informed or well advised and each acting in what they consider their own best interest.
3. A reasonable time is allowed for exposure in the open market.
4. Payment is made in cash in U. S. Dollars or in terms of financial arrangements comparable hereto.
5. The price represents a normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

## **INTENDED USE/USERS OF REPORT**

This appraisal is intended to assist the client, the County of Johnson, with financial decisions concerning the property.

## **INTEREST VALUED**

The property rights appraised in this report are those constituting the fee simple estate to the appraised property, subject to public and private encumbrances, covenants and restrictions which represent a portion of the potential ownership rights. The property is appraised under the assumption of responsible ownership. It is assumed that the property can be financed for purchase at present, prevalent market terms and rates.

## **EFFECTIVE DATE OF VALUE**

The effective date of the value estimate presented in this report is as of September 26, 2013.

## **DATE OF REPORT**

Work for this report began on September 26, 2013 and was completed on December 9, 2013.

## **APPRAISAL DEVELOPMENT AND REPORT PROCESS**

- Scope of the Appraisal

In preparing this appraisal, the appraisers did the following:

- 1) Inspected the subject site and interior as well as the exterior of the improvements.
- 2) Gathered information on the most recent comparable land, rentals and improved sales.
- 3) Confirmed and analyzed the data and applied the Market, Cost and Income approaches.
- 4) Consulted cost publications, such as Marshall & Swift, as well as information in the appraiser's files regarding the cost new of the subject and physical depreciation.

This Summary Appraisal Report is a brief recapitulation of the appraisers' data, analyses, and conclusions. Supporting documentation is retained in the appraisers' file.

## **HISTORY OF OWNERSHIP**

According to public records, title to the subject property is in the name of Johnson County as recorded in the County Deed Records. The subject property shows up on the earliest maps, the Sanborn Insurance maps for the year 1885 as the county jail and has been the property of the County since that time. No further research into ownership was considered necessary or was done.

## **DESCRIPTION OF REAL ESTATE APPRAISED**

### **LEGAL DESCRIPTION**

The subject property is legally described as recorded in the County Deed Records as follows:

Lots 1, 2, 3 & 4, Block 11, Original Cleburne

The Johnson County Central Appraisal District identifies the subject as R67428 and 126-2800-00285.

No current Survey for this tract was provided for this report.

### **LOCATION DESCRIPTION**

The subject property is located within the City of Cleburne. Cleburne is the county seat of Johnson County. According to the 2010 Census, Cleburne had a population of about 29,377. Cleburne is located about 35 miles southwest of Fort Worth and about 50 miles southwest of Dallas. Due to Cleburne's close proximity to the Metroplex, many residents work there.

Cleburne and Johnson County are experiencing steady growth in the residential, mostly as in-migration from the Metroplex, as well as in the commercial sector. Most of the new commercial growth has occurred along Highway 67. The economic outlook for the immediate future and long term for the area appears to be favorable. Continued steady growth is expected which will create the need for more residential units and with it, commercial space for community support businesses. The subject's neighborhood is considered to be the central portion of the City of Cleburne.

The subject property is located on South Mill Street, southwest of the intersection of Highway 171 & Highway 174 and West Chambers. There is currently zoning for C-1, commercial use, see map included. The subject is located is two blocks from the courthouse square. The immediate area of the subject consists of commercial entities's near the subject along Highway 67 also known as West Henderson Street and a portion of Chambers Street and Main Street also known as Highway 174 with nearby residential subdivisions located near the subject along interior streets.

## PROPERTY DESCRIPTION

The subject property consists of a 0.506 acres or 22,041 square foot site which is improved with jail building. The construction is solid wall masonry construction over a reinforced concrete slab foundation with a flat built up type roof. The building has been added onto with concrete block construction over a slab foundation.

The building was designed to function as a jail. The building is divided into a approximately 70 rooms with 36 cells, 1 kitchen, 2 dining rooms, 9 restrooms, a conference room, 9 offices and a dozen other rooms. The cells have restroom facilities. The building has central heat and air and is approximately 15,042 sf in size. The utilities available at the site are electricity, telephone, public water and a public sewer system. The building interior finish out is commercial grade carpeting in the offices and finished concrete floors in the prisoner areas. There are painted drywall partitions in the office sections with concrete block walls in the prisoner areas. The lighting provided by fluorescent ceiling fixtures.

The building has exterior security lights and security fencing. There are five grade level personnel doors on the south side of the building and one on the east into the lobby area. The paving and drives are concrete and asphalt which covers about a 19,450 sf area on the south side of the building. There is a six foot high, one foot thick rock wall around the perimeter of the site. There is fire equipment located throughout the building. There is peeling paint in some areas, at least one room had black mold growing on the wall. The west section of the building had ceiling tiles that had fallen and were littering the floor. There is a crack in the south wall that extends up the wall and down through the foundation. The city was contacted to see if the building had any building code violations and appraiser was told there were none known. Appraiser considers the building to currently be below market standards for occupation as a jail. Without a building inspection and contractor bids, the appraiser is unable to determine what it would cost to have the building in a habitable condition for it's designed use as jail again. The building is currently being used as storage.

Due to the age of the building, it is very likely that asbestos was used at some point in it's ongoing renovations during the it's lifetime. It is unknown what the cost to contain any asbestos that may be in the property would be, either in the case of renovation or demolition. An inspection is recommended to be provided by a professional company that specializes in asbestos as well as mold and other environmental issues. One such company that can provide a site survey is Austin Environmental, Inc is <http://www.austinenv.com/> They provide services throughout the state of Texas and can be reached at 979-229- 4385. Also noted was wall and slab foundation cracking. A structural engineer inspection is recommended to determine if these are significant issues.

According to FEMA's community maps the subject property's improvements do not appear to be within a flood hazard zone. However, they are adjacent to a creek and flood hazard area and a portion of the site may be within the flood hazard area. It should be noted that although it is considered very unlikely that the subject property's improvements would be subject to flooding due to their elevation, a prudent buyer would rely upon a survey to determine the subject property's exact relationship to any flood hazard area.

In summary, the subject site enjoys an average location along South Mill just southwest of the court house. The existing road network provides satisfactory access to and from the subject and visibility/exposure is considered good. The site's topographical features and ingress/egress are deemed satisfactory and all utilities are available or proximate to the site. Developments in the immediate area include the central business district with the majority of the land in the area being developed since the late 1800's and early 1900's. Developments nearby the subject along West Henderson and South Main include a variety of commercial developments taking advantage of the traffic flow.

Some renovations have taken place in the near vicinity of the subject including the Wright Building and the Liberty hotel.

## HIGHEST AND BEST USE

**Highest and Best Use As Though Vacant.** Considering the subject's location, it is believed that the highest and best use of the subject site as if vacant would be a commercial use. It has good visibility and frontage from a main thoroughfare in Cleburne. As population pressures in Johnson County create more residential subdivisions in the area, the traffic will continue to increase in front of the site and the need for commercial support businesses will increase consequently.

**Highest and Best Use as Improved.** The highest and best use of a property as improved may not always be the same as the highest and best use of a tract as if vacant. However, the improvements will continue to exist until the vacant site value exceeds the whole property value as improved. The land value very nearly equals the building value in it's 'as is' state. The cost to remove the current improvements might exceed the value of the land at this time; bids for demolition would be needed to determine the costs involved.

The improvements are designed to function as a jail. The overall construction of the building appears to be typical for a jail in the overall North Central Texas market area. The subject is within the central business district. The highest and best use, if the property were currently habitable as a jail, would be the continued use as a jail type income producing entity. However, due to the current condition of the subject property, it is not considered to be able to be used for it's designed purpose. Also, it is unknown what the cost of renovations would be to use the subject property as a jail. Current use 'as is' is as storage and therefore the Highest and Best Use would be as storage until such a time as renovations can be done.

It is very possible that an investor might purchase the property, and due to it's history of being the city's original jail in existence since the late 1880's, might renovate the subject improvements for use as apartments or a hotel use capitalizing on it's history to entice a customer base but would possibly require a zoning change.

As will be noted in the Income and Market Approaches, the subject's related improvements do have contributory value. Therefore, there is no alternative use which could legally, economically, and/or financially justify a change in proposed use. Therefore, the proposed use is considered to be the highest and best use of the property.

## SUMMARY OF ANALYSIS AND VALUATION

### MARKET APPROACH

When comparable market data is available, it should accurately reflect the attitudes of the typical buyers and sellers in the market place. When these are adjusted for differences noted, the indications are typically accurate. The appraisers were fortunate in this instance to be able to secure data on recent transactions of similar properties.

**Sales Comparison Approach.** A summary of the data on comparable improved sales is illustrated below.

Market Approach - Continued

Sale No.	Address City	Sales Price	Date of Sale	Bldg. S. F.	Age	Site S. F.	\$/SF
1	319 E Henderson St Cleburne	\$175,000	11/15/12	35,900	87	30,000	\$4.87
2	116 W Knox St Ennis, TX	\$85,000	7/26/13	5,125	93	2,874	\$16.59
3	116 S Covington St Hillsboro, TX	\$62,500	7/25/12	15,300	112	16,526	\$4.08
S	116 S Mill St Cleburne	NA	NA	15,042	~128	22,041	NA

The sales were all recent and no adjustment for market condition was considered appropriate. The sales were in the same or similar markets and no adjustment for location was made. The age of the comparable buildings was considered similar and were not adjusted. The estimated contributory value of the sites were adjusted accordingly. The sales had a similar mix of commercial/retail. The construction quality was not adjusted.

While there were no other jail facilities found in the search for comparables, the subject is currently being used as storage due to it's need for repairs. Therefore, other large, older buildings in similar condition were researched and used as comparable sales.

After making adjustments for differences the estimated value per unit for the subject property was \$10.11 per square foot. An adjustment grid has been included showing the indicated value on each comparable sale after adjustments were made.

<b>IMPROVED PROPERTIES ADJUSTMENT GRID</b>			
<b>SALE NUMBER:</b>	1	2	3
<b>PRICE PER UNIT:</b>	\$4.87	\$16.59	\$4.08
<b>ADJUSTMENTS</b>			
<b>ECONOMIC</b>			
Market Conditions:	0%	0%	0%
Condition of Sale:	0%	0%	0%
Terms of Sale:	0%	0%	0%
Adjusted Basis:	\$4.87	\$16.59	\$4.08
<b>PHYSICAL</b>			
Building Size:	20%	-30%	0%
Location:	0%	0%	0%
Condition/Age:	0%	0%	0%
Land Size/Value:	11%	40%	40%
Construction Qual:	0%	0%	0%
<b>NET ADJUSTMENT:</b>	31%	10%	40%
<b>INDICATED VALUE:</b>	\$6.38	\$18.25	\$5.71
<b>CONCLUSIONS:</b>			
Building Size:	15,042		
Estimated Value Per SF:	\$10.11		
Estimated Value of Subject Property:	\$152,128		
<b>VALUE INDICATED WHEN ROUNDED:</b>	<b>\$152,000</b>		

**INCOME APPROACH**

Rental No.	Address	\$/SF/ Annum	Size SF	Quality/ Condition	Location/ Occupancy	Expenses by Owner
1	216 S Main St Cleburne	\$2.79	5,167	Avg/Fair	Eq/100%	Taxes/Ins
2	110 E Chambers St Cleburne	\$2.00	4,000	Avg/Fair	Eq/100%	Taxes/Ins
3	206 S Main St Cleburne	\$2.50	3,825	Avg/Fair	Eq/100%	Taxes/Ins
Subj.	116 S Mill St Cleburne	\$0.00	3,917	Avg/Poor	Avg/100%	Taxes/Ins

A market survey was conducted for the purposes of this report. The reported rents range from \$2.00 to \$14 per square foot.

The rental comparables as well as the subject are retail spaces which are older buildings of similar age and construction which are not renovated and are reported by the agents to need repairs. Considering the rates found in the local market, and after adjusting for differences, the appraisers conclude that the estimated market rent for similar properties near the subject would be in the range of \$2.00 to \$2.79 per square foot per annum.

The subject is not currently in a condition to be occupied as a jail. The number of beds available would dictate what the rental income could be. Due to current condition, the low end of the range of the above rents in the market were used to indicate what the building could rent for as storage until such a time as it could be renovated or demolished.

The projected rents are within the range found in the market. Therefore, the proposed rental income will be used for the purposes of this valuation estimate. The Taxes, Insurance, Repairs, Maintenance and Reserve were based on an estimated market standard as was the Management.

In arriving at the estimated market rental, the appraisers have considered each of the rentals as to their overall similarity to the subject. The subject currently has no lease. If leased, the occupancy is expected to be within market norm and a conservative figure will be used for credit loss. The property might most likely be managed by the owner, however, a management fee typical in the market will be used for purposes of the income capitalization method.

The basis for all capitalization methods is net income divided by a rate of return equals value. The method of capitalization which is obtained directly from the market is the Direct Capitalization Method which is derived by dividing the net income by the sales price of the comparable sales resulting in a supportable overall capitalization rate or OAR. This method is considered the most reliable since it is a direct reflection of the overall rates which buyers and sellers are willing to accept in the market.



**DIRECT CAPITALIZATION**

Gross Potential Income			\$30,084
Less	Vacancy & Credit Loss	-23%	(\$6,919)
Effective Gross Income			\$23,165
Less	Taxes (estimated)		(\$4,220)
	Insurance (estimated)		(\$7,500)
	Management	-5%	(\$1,158)
	Utilities (Tenant)		\$0
	Repairs, Maintenance & Reserve	-5%	(\$1,158)
Total Expenses	(expenses as percent of EGI)	-60.59%	(\$14,036)
Net Operating Income			\$9,128
Capitalization Rate			10.0%
Indicated Value			\$91,282
<b>Indicated Value -</b>	<b>Rounded</b>		<b>\$91,300</b>

## RECONCILIATION AND VALUE CONCLUSION

The correlation or reconciliation process involves weighing the value indications provided by each applicable method in light of the dependability of each as a reflection of the probable actions of buyers and investors in the market place. The appraisers' final conclusion of value may coincide with one of the approaches, or it may reflect a weighing of the relative merits of each of the approaches in leading to a final conclusion of value. Three accepted methods of property valuation were applied in the appraisal process.

Consideration of the relative merits of each value indication involves reviewing each approach with respect to the reliability of the data used; the applicability of the approach to the type of property being appraised and the applicability of the approach in light of the definition of value sought in the appraisal. Following are the value indications resulting from each method.

**Market Approach.** The strength of this approach in any appraisal assignment is that if comparable market data is available, it should accurately reflect the attitudes of the typical buyers and sellers in the market place. When these are adjusted for differences noted, the indications are typically accurate. The appraisers were fortunate in this instance to be able to secure data on recent transactions of similar properties. From this data, various units of comparison were abstracted. This data is retained in the appraiser's files. The resulting value indication by this approach was as follows:

**\$ 152,000**

**Cost Approach.** The methodology of this approach basically involves estimating the contributory value of the subject improvements as well as the current fair market value of the land, as if vacant. These two value estimates are combined to yield the value indication by this approach. The potential weakness of this approach is that, in some instances, unit cost figures and depreciation are problematic to estimate. Physical depreciation is estimated through the observed condition of the improvements. Measures of obsolescence other than physical, if any, were accomplished through market abstracted methods whose dependability is strengthened by actual actions of the marketplace. Typically, the Cost Approach is often higher than either the Market or Income Approach. The Cost Approach is most effective when used in new construction. This approach is used mainly as support for the other two approaches when the improvements are not new. Due to the current condition, roof leaking, no recent renovations and the estimated age of the structure (~1885), the Cost Approach is not considered applicable. For the purposes of this summary report and the needs of the client, the Cost Approach was not deemed relevant.

**Income Approach, Direct Capitalization.** In this approach, comparable rentals, vacancy and collection factors and expenditures were abstracted from the marketplace and strengthened by historical data on the property when available. The data presented is supportive in all instances. That is, the rental rates, vacancy factors, expenses and capitalization rates are supported by the data presented herein and additional information kept in historical records within the appraisers' files.

The subject property was not considered to be in rentable condition as a jail on the date of inspection. Due to the uncertainty of the cost of renovation being supportable by any proposed tenants in the current market the rents it could command would be on the lowest end of the range as storage. Market rents were reviewed for properties in similar condition and applied in this approach. The value indication via this approach is as follows:

**\$ 91,300**

Reconciliation and Value Conclusion - Continued

The continued growth in the general Cleburne area population has created an steady need for properties such as the subject as professional office space near the courts and as retail space in the historical district which has helped to create fairly stable occupancy rates. Cleburne is considered a suburb to the Dallas/Fort Worth Metroplex area. The need for more space for community support business is considered to be steadily growing in this community.

The subject is a well-located commercial building in the city's downtown central business district. The subject property is designed to be a jail and if renovated is well located to produce an income, however, due to the subject's current condition, the Income Approach was not considered relevant due to the low rents the subject could command in it's current condition. Therefore, the most weight is placed upon the Market Sales Approach.

It is the opinion of these consultants, therefore, that the Market Value of the fee simple estate of the subject property as described herein, when considered in it's "as is" status, on a cash equivalency basis, **as of September 26, 2013** was:

**ONE HUNDRED FIFTY TWO THOUSAND DOLLARS**

**( \$ 152,000 )**

## CERTIFICATION

The undersigned certify that, to the best of their knowledge and belief, the following statements are true and correct and adhere to the requirements as set for them by the Appraisal Foundation.

The statements of fact contained in this report are true and correct.

The reported analysis, opinions, and conclusions are limited only by the reported assumptions and limiting conditions, and are our personal, unbiased professional analysis, opinions, and conclusions.

The undersigned have no present, contemplated or prospective interest in the property that is the subject of this report, and the undersigned have no personal interest or bias with the respect to the parties involved.

Our compensation is not contingent on an action or event resulting from this analysis, opinion, or conclusion in, or the use of, this report.

Our analysis, opinions, and conclusions were developed, and this report has been prepared in conformity with the requirements of the Code of Professional Ethics and Standards of Professional Practice of the Appraisal Foundation.

The Appraisers certify that the appraisal conforms to the Uniform Standards of Professional Practice (\*USPAP\*) adopted by the Appraisal Standards Board of the Appraisal Foundation, as amended.

The use of this report is subject to the requirements of the Appraisal Foundation relating to the review by their duly authorized representatives.

Dona L. Buie has made a personal inspection of the property that is the subject of this analysis and report.

The undersigned appraisers are not involved in the lending or collection function of the institution requesting the appraisal.

Dona L. Buie has made a personal, physical inspection of all comparable properties analyzed during the preparation of this report.

The employment of the undersigned was not conditioned on the appraisal producing a specific value, or a value within a given range, or the approval of a loan.

No person other than the undersigned, has provided significant professional assistance in the preparation of this appraisal report and the analysis, opinions, and conclusions contained herein.

As of the date of this report, Dona L. Buie has completed the requirements of the continuing education program of the Appraisal Foundation.

As of the date of this report Dona L. Buie is certified in the state of Texas as a General Real Estate Appraiser under Certification Number TX-1327327-G, with expiration date of April 30, 2015.

*Dona L. Buie*

\_\_\_\_\_  
Dona L. Buie

TX-1327327-G

Date: 12/6/2013

Appraisal Associates, LLC. (817) 279-8689

## ASSUMPTIONS AND LIMITING CONDITIONS

1. This is a Summary Appraisal Report which is intended to comply with the reporting requirements set forth under Standard Rule 2-2(b) of the Uniform Standards of Professional Appraisal Practice for a Summary Appraisal Report. As such, it might not include full discussions of the data, reasoning, and analyses that were used in the appraisal process to develop the appraiser's opinion of value. Supporting documentation concerning the data, reasoning, and analyses is retained in the appraisers' file. The information contained in this report is specific to the needs of the client and for the intended use stated in this report. The appraisers are not responsible for unauthorized use of this report.
2. No responsibility is assumed for legal or title considerations. Title to the property is assumed to be good and marketable unless otherwise stated in this report.
3. The property is appraised free and clear of any or all liens and encumbrances unless otherwise stated in this report.
4. Responsible ownership and competent property management are assumed unless otherwise stated in this report.
5. The information furnished by others is believed to be reliable. However, no warranty is given for its accuracy.
6. All engineering is assumed to be correct. Any plot plans and illustrative material in this report are included only to assist the reader in visualizing the property.
7. It is assumed that there are no hidden or unapparent conditions of the property, subsoil, or structures that render it more or less valuable. No responsibility is assumed for such conditions or for arranging for engineering studies that may be required to discover them.
8. It is assumed that there is full compliance with all applicable federal state, and local environmental regulations and laws unless otherwise stated in this report.
9. It is assumed that all applicable zoning and use regulations and restrictions have been complied with, unless a nonconformity has been stated, defined, and considered in this appraisal report.
10. It is assumed that all required licenses, certificates of occupancy or other legislative or administrative authority from any local, state, or national governmental or private entity or organization have been or can be obtained or renewed for any use on which the value estimates contained in this report are based.
11. Any sketch in this report may show approximate dimensions and is included to assist the reader in visualizing the property. Maps and exhibits found in this report are provided for reader reference purposes only. No guarantee as to accuracy is expressed or implied unless otherwise stated in this report. No survey has been made for the purpose of this report.
12. It is assumed that the utilization of the land and improvements is within the boundaries or property lines of the property described and that there is no encroachment or trespass unless otherwise stated in this report.

Assumptions and Limiting Conditions - Continued

13. The appraiser is not qualified to detect hazardous waste and/or toxic materials. Any comment by the appraiser that might suggest the possibility of the presence of such substances should not be taken as confirmation of the presence of hazardous waste and/or toxic materials. Such determination would require investigation by a qualified expert in the field of environmental assessment. The presence of substances such as asbestos, urea-formaldehyde foam insulation, or other potentially hazardous materials may affect the value of the property. The appraisers value estimate is predicated on the assumption that there is no such material on or in the property that would cause a loss in value unless otherwise stated in this report. No responsibility is assumed for any environmental conditions, or for any expertise or engineering knowledge required to discover them. The appraisers' descriptions and resulting comments are the result of the routine observations made during the appraisal process.

14. Unless otherwise stated in this report, the subject property is appraised without a specific compliance survey having been conducted to determine if the property is or is not in conformance with the requirements of the Americans with Disabilities Act. The presence of architectural and communications barriers that are structural in nature that would restrict access by disabled individuals may adversely affect the property's value, marketability, or utility.

15. Any proposed improvements are assumed to be completed in a good workmanlike manner in accordance with the submitted plans and specifications.

16. The distribution, if any, of the total valuation in this report between land and improvements applies only under the stated program of utilization. The separate allocations for land and buildings must not be used in conjunction with any other appraisal and are invalid if so used.

17. Possession of this report, or a copy thereof, does not carry with it the right to publication. It may not be used for any purpose by any person other than the party to whom it is addressed without the written consent of the appraiser, and in any event, only with proper written qualification and only in its entirety.

18. Neither all nor any part of the contents of this report (especially any conclusions as to value, the identity of the appraisers, or the firm with which the appraisers are connected) shall be disseminated to the public through advertising, public relations, news sales, or other media without prior written consent and approval of the appraiser.

**ADDENDUM**